

# eCopy ScanStation v5 Supported Device List

## For Konica Minolta Devices

The following Konica-Minolta devices are supported by the eCopy ShareScan® v5 for ScanStation:

<b><u>Color*</u></b>	<b><u>Minimum Firmware</u></b>	<b><u>TWAIN Driver Version</u></b>
bizhub C203/C253/C353	v21	3.1.2.22_NoGUI
bizhub C250/C252/C450	vGM0-08 vGM0-09 for C252	3.1.2.22_NoGUI
bizhub C351/C352	vGM0-08	3.1.2.22_NoGUI
bizhub C451/C550/C650	v6M	3.1.2.22_NoGUI
bizhub C452/C552/C652	A0P00Y0-0023-G00-04 EC04 (G00-47 for C452)	3.1.2.22_NoGUI
bizhub C360/C280/C220	G00-58	3.1.2.22_NoGUI
<b><u>Black &amp; White</u></b>	<b><u>Minimum Firmware</u></b>	<b><u>TWAIN Driver Version</u></b>
bizhub 200/250/350	v31_UL	3.1.2.22_NoGUI
bizhub 360/420/500	v31_UL	3.1.2.22_NoGUI
bizhub 361/421/501	v11	3.1.2.22_NoGUI
bizhub 600/750	v30_UJ	3.1.2.22_NoGUI
bizhub 601/751	A0PN0Y0-0100-G00-11	3.1.2.22_NoGUI
bizhub 920/1050e	v20 v30 for 1050e	3.1.2.22_NoGUI
bizhub 223/283/363/423	G00-26	3.1.2.22_NoGUI

### Notes

Please note the following configurations are not supported by the ScanStation:

- ISIS drivers are not supported by this ScanStation (For a list of ISIS supported scanners visit the Scanner Supported Device List)
- VRS TWAIN is not supported by ScanStation
- EFI Fiery TWAIN is not supported by ScanStation